DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004719 Address: 333 Burma Road **Date Inspected:** 19-Nov-2008

City: Oakland, CA 94607

OSM Arrival Time: 730 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Erik Prue was present to perform Ultrasonic Testing (UT) of Orthotropic Box Girder (OBG) components, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

Inspectors office: QA Inspector attended health and safety confined space training. Caltrans (MACTEC) QA Inspectors are still not approved to enter the confined spaces for inspections.

OBG Assembly Bay # 2

Quality Assurance (QA) inspector arrived at ZPMC in Shanghai China for observation of Orthotropic Bridge Girders (OBG) and Self Anchored Suspension (SAS) Bridge. QA inspector received notification from day shift task leader to perform conventional Ultrasonic (A scan) Inspection for tack welds on deck panels. The inspection is preliminary prior to using the phased array system to verify indications found with conventional Ultrasonic testing. QA inspector performed UT on deck panel DP189-001, 5 ribs, 10 welds, 260 total tack welds inspected. A total of 26 indications were present and marked on top of u-ribs. Please see U-rib Deck Panel Tack Weld Assessment report dated 19 November, 2008 for specific locations of indications.

No other activities observed.

Summary of Conversations:

No signifigant conversations this day.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Peter Dauterman, 15002199593, who represents the Office of Structural Materials for your project.

Inspected By:	Prue, Erik	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer